

MAXNET II® - MP3BAS - Ultra-dense Active Chassis Only

FIRMWARE UPDATE NOTICE

Version:

- ▶ mn2s.1.6.54

Issued:

- ▶ Jan 17, 2025

Fixes:

- ▶ Changing analog alarm threshold values for some modules would sometimes cause the chassis to reboot was fixed
 - ▶ Decreased RAM usage that was causing some chassis to lock-up and require a system reboot
-

Version:

- ▶ mn2s.1.6.37

Issued:

- ▶ June 26, 2014

Fixes:

- ▶ Slot 9 disappearing when Slot 8 & 9 had MPSA8x2 or MPSABCNC modules installed
- ▶ Log timing stamp issue
- ▶ NTC time server not working

Known Issues:

- ▶ Latest versions of Internet Explorer® will not display graphics correctly. It is a display issue only. No function loss
- ▶ LED status can take up to 1 minute to display state change
- ▶ Re-seating module MPSA8x2 or MPSABCNC before GUI clear causes LED to default to no alarm even if an alarm is present



Service and Support

Contact ATX Networks

Please contact ATX Technical Support for assistance with any ATX products. Please contact ATX to obtain a valid RMA number for any ATX products that require service and are in or out-of-warranty before returning a failed module to ATX.

TECHNICAL SUPPORT

Tel: 289.204.7800 – press 1
Toll-Free: 866.YOUR.ATX (866.968.7289) USA and Canada only
Email: support@atx.com

SALES ASSISTANCE

Tel: 289.204.7800 – press 2
Toll-Free: 866.YOUR.ATX (866.968.7289) USA and Canada only
Email: insidesales@atx.com

FOR HELP WITH AN EXISTING ORDER

Tel: 289.204.7800 – press 3
Toll-Free: 866.YOUR.ATX (866.968.7289) USA and Canada only
Email: orders@atx.com
Web: www.atx.com

MAXNET® II is a registered trademark of ATX in the United States and/or other countries. Products or features contained herein may be covered by one or more U.S. or foreign patents. Other non-ATX product and company names in this manual are the property of their respective companies.

