

MAXNET II® - MP3FA - F Optics Active Chassis FIRMWARE UPDATE NOTICE

D3.1/CCAP™
Compliant

1.2 GHz

Version:

- ▶ mn2f.1.6.37

Issued:

- ▶ June 18, 2014

Fixes:

- ▶ Selecting "save changes" on the CHASSIS tab doesn't affect the relay state.
- ▶ SNMP heCommonLog Table correctly increments now.
- ▶ Log timing stamp going out of sequence.
- ▶ UTC time server field in configuration not adding time offset.
- ▶ Amplifier modules correctly display temperature thresholds HI=60,HIHI=70.
- ▶ Corruption of MAC/persistent memory when power cycling.
- ▶ Telnet soft-reboot command corrupting persistent settings.
- ▶ Persistent memory corrupting when upgrading firmware.
- ▶ SNMP traps not being generated.
- ▶ MPRFA/B modules correctly show dBmV instead of dBm on GUI.

Known Issues:

- ▶ MPRFA/B - using front pushbutton to change default control state doesn't store in persistent memory. Need to change control state using GUI or SNMP sets.
- ▶ MPRX-8F - OptRx alarms generated on GUI log display "input B", should be "OptRx Input Status" or "OptRx Input Power".
- ▶ Latest versions of Internet Explorer® will not display graphics correctly. It is a display issue only. No function loss.



Service & Support

Contact ATX Networks

Please contact ATX Technical Support for assistance with any ATX products. Please contact ATX Customer Service to obtain a valid RMA number for any ATX products that require service and are in or out-of-warranty before returning a failed module to the factory.

TECHNICAL SUPPORT

Tel: 289.204.7800 – press 1
Toll-Free: 866.YOUR.ATX (866.968.7289) USA & Canada only
Email: support@atx.com

SALES ASSISTANCE

Tel: 289.204.7800 – press 2
Toll-Free: 866.YOUR.ATX (866.968.7289) USA & Canada only
Email: insidesales@atx.com

FOR ASSISTANCE WITH AN EXISTING ORDER

Tel: 289.204.7800 – press 3
Toll-Free: 866.YOUR.ATX (866.968.7289) USA & Canada only
Email: orders@atx.com
Web: www.atx.com

Although every effort has been taken to ensure the accuracy of this document it may be necessary, without notice, to make amendments or correct omissions.

MAXNET® II is a registered trademark of ATX in the United States and/or other countries. Products or features contained herein may be covered by one or more U.S. or foreign patents. Other non-ATX product and company names in this manual are the property of their respective companies.

© 2019 by ATX Networks Corp. and its affiliates (collectively "ATX Networks Corp."). All rights reserved. This material may not be published, broadcast, rewritten, or redistributed. Information in this document is subject to change without notice.



8-1602 Tricont Avenue, Whitby, ON L1N 7C3 Canada
Tel: 289.204.7800 | Toll-Free: 866.YOUR.ATX (866.968.7289)
www.atx.com support@atx.com