

MAXNET II° - GENERATION 2 COMMUNICATION MODULE FIRMWARE UPDATE NOTICE

D3.1/CCAP™ Compliant

1.2 GHz

Version:

▶ 1.9

Issued:

▶ Sep 25, 2018

Fixes:

- ▶ SNMP requests for unsupported OIDs now correctly respond with a 'noSuchObject'
- ▶ Corrected an issue where encryption and authentication settings could become corrupt for e-mail notification
- ▶ Added E-mail notification encryption and authentication drop-down selections
- ▶ Added E-mail Log to the Reports page to help diagnose issues with E-mail notifications
- ▶ Corrected authentication errors when attempting to upgrade using FTP
- ▶ All firmware upgrades will now automatically reboot the device after the upgrade is complete
- ▶ Corrected FTP firmware upgrades displaying 2 upgrade buttons
- ▶ Corrected Local File Upload displaying 2 firmware file information fields

Version:

▶ 1.6

Issued:

Dec 8, 2017

Fixes:

▶ Corrected an issue when requesting the full SNMP ISO caused a timeout

Version:

▶ 1.5

Issued:

Jul 14, 2017

Fixes:

▶ Initial Release

Global Services & Support

Contact ATX Networks

Please contact ATX Technical Support for assistance with any ATX products. Please contact ATX Customer Service to obtain a valid RMA number for any ATX products that require service and are in or out-of-warranty before returning a failed module to the factory.

Tel: (905) 428-6068 – press *1

Toll Free Fax: 866.YOUR.ATX (866.968.7289) USA & Canada only

Email: <u>support@atxnetworks.com</u>

Web: <u>www.atx.com</u>

Although every effort has been taken to ensure the accuracy of this document it may be necessary, without notice, to make amendments or correct omissions. Specifications subject to change without notice.

MAXNET® II is a registered trademark of ATX in the United States and/or other countries. Products or features contained herein may be covered by one or more U.S. or foreign patents. Other non-ATX product and company names in this manual are the property of their respective companies.



