

OCML2 MODULE FIRMWARE RELEASE NOTES 1.2

Release:

- ▶ 1.2

Issued:

- ▶ January 17, 2022

Added New Feature:

- ▶ Optical power reading accuracy improved. Optical back reflections do not impact switch power readings
- ▶ Support of warm reboot (requires controller rev 3.4 or later). Gives user option in UI to reset the OCML2 module without impacting service or configuration parameters in order to restore communications to a non-responding module
- ▶ Wait to Restore on switch now functions as per SCTE MIB
- ▶ Unit will not switch to secondary path if secondary power reading is below its threshold, regardless of what is measured on primary path

Service & Support

Contact ATX Networks

Please contact ATX Technical Support for assistance with any ATX products.

TECHNICAL SUPPORT

Tel: 289.204.7800 – press 1
Toll-Free: 866.YOUR.ATX (866.968.7289) USA & Canada only
Email: support@atx.com

SALES ASSISTANCE

Tel: 289.204.7800 – press 2
Toll-Free: 866.YOUR.ATX (866.968.7289) USA & Canada only
Email: insidesales@atx.com

FOR ASSISTANCE WITH AN EXISTING ORDER

Tel: 289.204.7800 – press 3
Toll-Free: 866.YOUR.ATX (866.968.7289) USA & Canada only
Email: orders@atx.com
Web: www.atx.com



8-1602 Tricont Avenue, Whitby, ON L1N 7C3 Canada
Tel: 289.204.7800 | Toll-Free: 866.YOUR.ATX (866.968.7289)
www.atx.com support@atx.com