



Product Advisory

Date: August 2, 2024
Product: RF Management, OSP Taps
Reason: Manufacture Discontinue (MD) Notification

ATX formally announces the Manufacture Discontinue (MD) and End-of-Life (EOL) Notification for several RF Management products that are part of the MAXNET, MAXNET II, SignalOn and SCN portfolios, as well as a variety of Hardline Taps. These legacy products are used less as the industry transitions to Distributed Access Architectures. Due to the decreased demand, ATX is reducing variations among these products for greater production efficiency. ATX will no longer be able to support new sales of these products beyond the dates shown below.

Product-Specific Lifecycle Information

While we strive to follow the ATX Product Hardware and Software Lifecycle Support Policy (see last page), some products may not be manufacturable beyond what is in stock. All remaining stock can be ordered and shipped within the last-buy timeframe — in some cases this date can be extended. Contact ATX for a case-by-case consideration for products that are out of stock but are still desired. The table below includes general lifecycle milestones with associated dates.

Lifecycle Milestones

Milestone	Definition	Date
Lifecycle Announcement	Communication date announcing start of MD and the end-of-life process	August 2, 2024
End-of-Sale (EOS)	Last day on which affected product SKUs in this communication can be ordered from ATX. ATX Care will continue to support technical repair or replacement of affected products still under warranty per terms covered at time of sale.	January 31, 2025
End-of-Service-Life (EOSL)	Date of the end of all non-warranty support, repair and replacement (excluding any Extended Warranty or SLA)	January 31, 2028

Products included in this Bulletin

SKUs affected by this notice include:

Product Line	Discontinued SKU	Suggested Replacement SKU
HFC - Amplifiers & Accessories	QRFP/B EU CORD	no alt
HFC - Amplifiers & Accessories	QRFP/B P.S.	no alt
HFC - Amplifiers & Accessories	JXP-A-00	no alt
HFC - Amplifiers & Accessories	JXP-A-01	no alt
HFC - Amplifiers & Accessories	JXP-A-02	no alt
HFC - Amplifiers & Accessories	JXP-A-03	no alt
HFC - Amplifiers & Accessories	JXP-A-04	no alt
HFC - Amplifiers & Accessories	JXP-A-05	no alt
HFC - Amplifiers & Accessories	JXP-A-06	no alt
HFC - Amplifiers & Accessories	JXP-A-07	no alt
HFC - Amplifiers & Accessories	JXP-A-08	no alt
HFC - Amplifiers & Accessories	JXP-A-09	no alt
HFC - Amplifiers & Accessories	JXP-A-10	no alt
HFC - Amplifiers & Accessories	JXP-A-11	no alt
HFC - Amplifiers & Accessories	JXP-A-12	no alt
HFC - Amplifiers & Accessories	JXP-A-13	no alt
HFC - Amplifiers & Accessories	JXP-A-14	no alt
HFC - Amplifiers & Accessories	JXP-A-15	no alt
HFC - Amplifiers & Accessories	JXP-A-16	no alt
HFC - Amplifiers & Accessories	JXP-A-17	no alt
HFC - Amplifiers & Accessories	JXP-A-18	no alt
HFC - Amplifiers & Accessories	JXP-A-19	no alt
HFC - Amplifiers & Accessories	JXP-A-20	no alt
HFC - Amplifiers & Accessories	JXP-A-21	no alt
HFC - Amplifiers & Accessories	JXP-A-22	no alt
HFC - Amplifiers & Accessories	JXP-A-23	no alt
HFC - Amplifiers & Accessories	JXP-A-24	no alt
HFC - Amplifiers & Accessories	JXP-A-25	no alt
HFC - Amplifiers & Accessories	JXP-A-TERM	no alt

Product Line	Discontinued SKU	Suggested Replacement SKU
HFC - Amplifiers & Accessories	QPAIR1000-17G/48	QPAIR1000-23GPH/AC
HFC - Amplifiers & Accessories	QPAIR1000-19GP/48	QPAIR1000-23GPH/AC
HFC - Amplifiers & Accessories	QPAIR1000-19GP/AC	QPAIR1000-23GPH/AC
HFC - Amplifiers & Accessories	QPAIR1000-23GP/AC/48	QPAIR1000-23GPH/AC
HFC - Amplifiers & Accessories	QRFB065-24/4/48	no alt (EOL immediately)
HFC - Amplifiers & Accessories	QRFB065-24/4/AC	no alt (EOL immediately)
HFC - Amplifiers & Accessories	QRFB065-29/4/48	no alt (EOL immediately)
HFC - Amplifiers & Accessories	QRFB065-29/4/AC	no alt (EOL immediately)
OSP - SGC 1.2GHz Taps	GTSG-RW-2-F20R17-STD	GTSG-RW-2-F23R17-FP
OSP - SGC 1.2GHz Taps	GTSG-RW-2-F23R17-STD	GTSG-RW-2-F23R17-FP
OSP - SGC 1.2GHz Taps	GTSG-RW-2-F23R20-STD	GTSG-RW-2-F23R17-FP
OSP - SGC 1.2GHz Taps	GTSG-RW-2-F35R20-FP	GTSG-RW-2-F26R20-FP
OSP - SGC 1.2GHz Taps	GTSG-RW-2-F35R20-STD	GTSG-RW-2-F32R20-STD
OSP - SGC 1.2GHz Taps	GTSG-RW-4-F20R17-FP	GTSG-RW-4-F23R20-FP
OSP - SGC 1.2GHz Taps	GTSG-RW-4-F23R17-FP	GTSG-RW-4-F23R20-FP
OSP - SGC 1.2GHz Taps	GTSG-RW-4-F26R20-FP	GTSG-RW-4-F23R20-FP
OSP - SGC 1.2GHz Taps	GTSG-RW-4-F32R20-FP	GTSG-RW-4-F29R20-FP
OSP - SGC 1.2GHz Taps	GTSG-RW-4-F35R20-FP	GTSG-RW-4-F29R20-FP
OSP - SGC 1.2GHz Taps	GTSG-RW-4-F35R20-STD	GTSG-RW-4-F29R20-FP
OSP - SGC 1.2GHz Taps	GTSG-RW-8-F23R20-FP	GTSG-RW-8-F23R17-FP
OSP - SGC 1.2GHz Taps	GTSG-RW-8-F35R20-FP	GTSG-RW-8-F32R20-FP
OSP - XST 1.8GHz Taps	XSA-CE-1218-02	XSA-XCE-1800-03
OSP - XST 1.8GHz Taps	XSA-CE-1218-04	XSA-XCE-1800-06
OSP - XST 1.8GHz Taps	XSA-CE-1218-06	XSA-XCE-1800-06
OSP - XST 1.8GHz Taps	XSA-CE-1218-08	XSA-XCE-1800-06
OSP - XST 1.8GHz Taps	XSA-CE-1218-10	XSA-XCE-1800-09
OSP - XST 1.8GHz Taps	XSA-CE-1218-12	XSA-XCE-1800-09
OSP - XST 1.8GHz Taps	XSA-CE-1218-14	XSA-XCE-1800-09
OSP - XST 1.8GHz Taps	XSA-CE-1218-16	XSA-XCE-1800-09
OSP - XST 1.8GHz Taps	XSA-CE-1218-18	XSA-XCE-1800-09
OSP - XST 1.8GHz Taps	XSA-CE-1218-20	XSA-XCE-1800-09
OSP - XST 1.8GHz Taps	XSA-CE-1218-22	XSA-XCE-1800-09

Product Line	Discontinued SKU	Suggested Replacement SKU
OSP - XST 1.8GHz Taps	XSA-CE-1800-02	XSA-XCE-1800-03
OSP - XST 1.8GHz Taps	XSA-CE-1800-04	XSA-XCE-1800-06
OSP - XST 1.8GHz Taps	XSA-CE-1800-06	XSA-XCE-1800-06
OSP - XST 1.8GHz Taps	XSA-CE-1800-08	XSA-XCE-1800-06
OSP - XST 1.8GHz Taps	XSA-CE-1800-10	XSA-XCE-1800-09
OSP - XST 1.8GHz Taps	XSA-CE-1800-12	XSA-XCE-1800-09
OSP - XST 1.8GHz Taps	XSA-CE-1800-14	XSA-XCE-1800-09
OSP - XST 1.8GHz Taps	XSA-CE-1800-16	XSA-XCE-1800-09
OSP - XST 1.8GHz Taps	XSA-CE-1800-18	XSA-XCE-1800-09
OSP - XST 1.8GHz Taps	XSA-CE-1800-20	XSA-XCE-1800-09
MAXNET - Passives	MN1RK	MN1
MAXNET - Passives	MN3	MN5B
MAXNET - Passives	MN4CSF	MN4-2TCPFH
MAXNET - Passives	MNTRAY	no alt
SCN	BP-8710-R-A	no alt
SCN	BP-8710-R-B	no alt
SCN	BP-8710-R-C	no alt
SCN	BP-8710-R-D	no alt
SCN	BP-8710-RG1	no alt
SCN	BP-8710-RG2	no alt
SCN	BP-8720-3R	no alt
SCN	BP-8720-4R	no alt
SCN	BP-8720-R-A	no alt
SCN	BP-8720-R-C	no alt
SCN	BP-8720-W-A	no alt
SCN	BP-8730	no alt
SCN	BRF-8745-R	no alt
SCN	BRF-8745-W	no alt
SCN	BWH-9060-55	no alt
SCN	BWH-9060-55-Q	no alt
SCN	BWH-9060-A	no alt
SCN	BWH-9060-A-Q	no alt

Product Line	Discontinued SKU	Suggested Replacement SKU
SCN	BWH-9060-C	no alt
SCN	BWH-9060-D	no alt
MAXNET II - Actives	MPBAR	no alt
MAXNET II - Actives	MP-BLANK-19	no alt
MAXNET II - Actives	MPRFA/B	MPRFA/BFH
MAXNET II - Actives	QMP1000-28GPF	QMP1000-34GPF
MAXNET II - Actives	QMP1000-31GPF	QMP1000-34GPF
MAXNET II - Actives	QMP1000-35GPF	QMP1218-40PF / QMP1218-44PF
MAXNET II - Actives	QMP1000-35PF	QMP1218-40PF / QMP1218-44PF
MAXNET II - Actives	QMP1000-40PF	QMP1218-40PF / QMP1218-44PF
MAXNET II - Actives	QMP1218-35GPF	QMP1218-44PF
MAXNET II - Actives	QMP1218-35PF	QMP1218-44PF
MAXNET II - Connectors	MPADPMB	MPADPM
MAXNET II - Connectors	MPCINT	no alt
MAXNET II - Connectors	MPCONKIT-CQ	MPCONKIT
MAXNET II - Connectors	MPM-F	no alt
MAXNET II - Passives	MP20-3DC	MP20-3DCH
MAXNET II - Passives	MP20-4DCN	MP20-3DCH
MAXNET II - Passives	MP2-3	MP2-3PH
MAXNET II - Passives	MP2-3H	MP2-3PH
MAXNET II - Passives	MP3-20DCF	MP20-3DCH
MAXNET II - Passives	MP3-20DCFH	MP20-3DCH
MAXNET II - Passives	MP3R	MP3B
MAXNET II - Passives	MP4-2C	MP4-2CH
MAXNET II - Passives	MP4-2S	MP4-2SH
MAXNET II - Passives	MP4-2SC	MP4-2SCH
MAXNET II - Passives	MP6-12DCH	no alt
MAXNET II - Passives	MP6C	MP6CH
MAXNET II - Passives	MPBC4NC-2H	MPBC3NC-2H
MAXNET II - Passives	MPBC4NCH	MPBC3NC-2H
MAXNET II - Passives	MPBCNCH	MPBC3NC-2H
MAXNET II - Passives	MPDX65FH	no alt

Product Line	Discontinued SKU	Suggested Replacement SKU
MAXNET II - Passives	MPPAD75T	no alt
MAXNET II - Passives	MPRB	no alt
SignalOn - Actives	N-ACC-CBL-DC-DC	N-MV48DC
SignalOn - Actives	N-C20VYB	MP3BA
SignalOn - Actives	N-MAF22RA	QMP200-28LF
SignalOn - Actives	N-MAF30FA	QMP1218-40PF
SignalOn - Actives	N-MAF30FAH	QMP1218-40PF
SignalOn - Actives	N-MRFSM2-F	MPRFA/BFH
SignalOn - Actives	N-MV48DC	MPDC
SignalOn - Actives	N-MVUVAC-N	MPAC-110
SignalOn - Passives	N-ACC-AP-0P25	N-ACC-AP-01
SignalOn - Passives	N-ACC-AP-0P5	N-ACC-AP-01
SignalOn - Passives	N-ACC-AP-0P75	N-ACC-AP-01
SignalOn - Passives	N-ACC-AP-10P5	N-ACC-AP-10
SignalOn - Passives	N-ACC-AP-11P5	N-ACC-AP-12
SignalOn - Passives	N-ACC-AP-12P5	N-ACC-AP-12
SignalOn - Passives	N-ACC-AP-13P5	N-ACC-AP-14
SignalOn - Passives	N-ACC-AP-14P5	N-ACC-AP-14
SignalOn - Passives	N-ACC-AP-15P5	N-ACC-AP-16
SignalOn - Passives	N-ACC-AP-16P5	N-ACC-AP-16
SignalOn - Passives	N-ACC-AP-17P5	N-ACC-AP-18
SignalOn - Passives	N-ACC-AP-18P5	N-ACC-AP-18
SignalOn - Passives	N-ACC-AP-19P5	N-ACC-AP-20
SignalOn - Passives	N-ACC-AP-1P25	N-ACC-AP-01
SignalOn - Passives	N-ACC-AP-1P5	N-ACC-AP-02
SignalOn - Passives	N-ACC-AP-1P75	N-ACC-AP-02
SignalOn - Passives	N-ACC-AP-20P5	N-ACC-AP-20
SignalOn - Passives	N-ACC-AP-21P5	N-ACC-AP-22
SignalOn - Passives	N-ACC-AP-22P5	N-ACC-AP-22
SignalOn - Passives	N-ACC-AP-23P5	N-ACC-AP-24
SignalOn - Passives	N-ACC-AP-24P5	N-ACC-AP-24
SignalOn - Passives	N-ACC-AP-25P5	N-ACC-AP-26

Product Line	Discontinued SKU	Suggested Replacement SKU
SignalOn - Passives	N-ACC-AP-2P5	N-ACC-AP-02
SignalOn - Passives	N-ACC-AP-3P5	N-ACC-AP-04
SignalOn - Passives	N-ACC-AP-4P5	N-ACC-AP-04
SignalOn - Passives	N-ACC-AP-5P5	N-ACC-AP-06
SignalOn - Passives	N-ACC-AP-6P5	N-ACC-AP-06
SignalOn - Passives	N-ACC-AP-7P5	N-ACC-AP-08
SignalOn - Passives	N-ACC-AP-8P5	N-ACC-AP-08
SignalOn - Passives	N-ACC-AP-9P5	N-ACC-AP-10
SignalOn - Passives	N-C04HNB	N-C08HNB
SignalOn - Passives	N-C20DOORCARD	no alt
SignalOn - Passives	N-SOBAR	no alt

Note: MAXNET, SignalOn and SCN are trademarks of ATX.

ATX Product Hardware and Software Lifecycle Support Policy

Lifecycle	Software	Hardware
Active	<ul style="list-style-type: none"> • Software generally available (GA) for deployment • Standard Warranty terms apply for 90 days • ATX Care Support Plan required thereafter • Corrective content via Maintenance releases 	<ul style="list-style-type: none"> • Hardware currently manufactured and available for order • Standard Warranty and ATX Care terms apply
Inactive (Software) or MD – Manufacture Discontinued	<ul style="list-style-type: none"> • Targeted corrective content (Outage, BC) with ATX Care 	<ul style="list-style-type: none"> • Not available for new deployments and expansions • Customer-specific exceptions considered based on MP5A
Retired (Software) or EOL – End of Life (Hardware)	<ul style="list-style-type: none"> • No corrective content available • Emergency Recovery only (no RCA) with ATX Care Support Plan • No Security patching 	<ul style="list-style-type: none"> • ATX no longer supports the advanced replacement of hardware in instances where existing stock is exhausted but MAY provide a best-effort repair service
EOSL – End-of-Service-Life	<ul style="list-style-type: none"> • ATX no longer supports the product 	<ul style="list-style-type: none"> • ATX no longer supports hardware — certain hardware may be removed from software releases

Note: Customer and contract-specific terms and conditions may apply that supersede the above policy intervals.

Global Services & Support

Contact ATX Networks

Please contact ATX Technical Support for assistance with any ATX products. Please contact ATX Customer Service to obtain a valid RMA number for any ATX products that require service and are in or out-of-warranty before returning a failed module to the factory.

Toll Free: 866.YOUR.ATX (866.968.7289) USA & Canada only – Select Option 1

Tel: +1 289.204.7800

Email: support@atx.com

Web: www.atx.com

As always, please contact your ATX Sales and/or support primes for additional information.

ATX would like to thank you in advance for your understanding and continued support.

Purchase Orders

Email: orders@atx.com